

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

JV1360
NNE
> 1
1.718 mi.
9069 ft.

MANHOLE 63639
EAST 2ND ST & KINGS H-WAY
BROOKLYN, NY

NY Spills S104194816
N/A

Site 2 of 2 in cluster JV

Relative:
Higher

Actual:
24 ft.

SPILLS:

Name: MANHOLE 63639
Address: EAST 2ND ST & KINGS H-WAY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9906821 / 1999-11-09
Facility ID: 9906821
Facility Type: ER
DER Facility ID: 186670
Site ID: 226143
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-09-08
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1999-09-08
CID: 211

Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-09-08
Spill Record Last Update: 2000-05-24
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: STEPHEN CRIBBEN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL con ed e2mis notes: 1 pt. unknown oil on 100 gallons water in MH63639. Taken a sample, cleanup pending test results. <1ppm LSN#99-09350 Cleanup completed and tag removed. Incident is closed. "

Remarks: "1 PINT UNK OIL 100 GALS WATER - CLEAN UP PENDING LAB RESULTS CON ED 127657"

All Materials:

Site ID: 226143
Operable Unit ID: 1081122
Operable Unit: 01
Material ID: 299541
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported